



+5V from controller board
 To clutch solenoid
 To exit sensor input of controller board
 To manual paper feed sensor input of controller board
 To paper in sensor input of controller board
 Output of new paper in sensor
 Ground
 Ground
 Operator's panel data line
 Hall sensor output from motor board
PRINTER

Sheet: /		
File: haxmark.sch		
Title:		
Size: A4	Date:	Rev:
KiCad E.D.A. kicad (2015-02-26 BZR 5453)-product		Id: 1/1